UNCLASSIFIED

REPEATER, TELEGRAPH TH-38 ()/G

Report No. 4

FOURTH QUARTERLY PROGRESS REPORT 1 DECEMBER 1962 TO 1 MARCH 1963

Signal Corps Contract DA-36-039, SC87254

Prepared for: U.S. Army Signal Research & Development Laboratory

Fort Monmouth, New Jersey

Prepard by: Radiation Incorporated

Melbourne, Florida

UNCLASSIFIED



X

\$1,60

QUALIFIED REQUESTORS MAY OBTAIN COPIES OF THIS REPORT FROM ASTIA

(4) \$1.60 (5) 734300

Report No. 4

(REPEATER, TELEGRAPH TH-38 ()/G
DNA DECIMETER & Progress reptine 4, 1Dec 62-1 marches
Covering Period 1 December 1962 to 1 March 1963
Signal Corps Contract DA 36,039, SC87254
Signal Corps Technical Requirement SCL-4067 dated 28 October 1958 Amendment No. 1 dated September 1960 (C) Project No. 3831 06 001 07
(Project No. 3B21,007,001,03
) 14P-
Object: The objective of this Contract is to develop a highly reliable Telegraph
Repeater for field use.
Report Written By: R. D. Squires
$\mathcal{O}(\mathcal{M})$
Prepared By: Radiation Incorporated

Melbourne, Florida

TABLE OF CONTENTS

Section	Title	Page
I	PURPOSE	1
II	ABSTRACT	2
III	PUBLICATIONS, PEPORTS AND CONFERENCES	3
	A. Publications B. Reports C. Conferences	3 3 3
IV	FACTUAL DATA	6
	A. Checkout of Engineering Test Models B. System Design	6 9
v	CONCLUSIONS	12
VI	PROGRAM FOR NEXT INTERVAL	13
VII	KEY PERSONNEL	14
	DISTRIBUTION LIST	

LIST OF ILLUSTRATIONS

FIGURE NO.		Page
ī	REPEATER TELEGRAPH, TH-38 ()/G	10

I PURPOSE

This project consists of the design, development and fabrication of 20 Telegraph Repeaters TH-38 ()/G along with documentation as required by the contract. The repeater must be designed to operate in two different modes; full duplex and half duplex-full duplex. Using the converter, circuits of differing characteristics may be interconnected and normal traffic established.

A prime requisite of the contract is to achieve a Mean Time Between Failure of 57,000 hours. Fabrication of the twenty repeaters will be divided into three phases. Two engineering test models will be fabricated and submitted to USASRDL for operational and environmental evaluation. Then eight more engineering test models, incorporating any required changes, will be built and put on life test along with the first two repeaters. The final phase will consist of the fabrication of ten service test models for field use.

of telegraph repeater TH-386, 16.

The first two engineering test models were assembled and successfully tested electrically, to the Test and Evaluation Plan. Vibration testing was performed, and unit resonance at approximately 35 cycles was detected. A mechanical redesign was begun, in order to insure compliance with the mechanical requirements of SCL-4067.

III PUBLICATIONS, REPORTS AND CONFERENCES

A PUBLICATIONS

There were no publications presented as a result of the program during the fourth quarter.

B REPORTS

- (1) Monthly Performance Summaries were prepared and submitted to USAERDL.
 - (2) Quarterly Report #3 was submitted to USAERDL.

C CONFERENCES

(1) Messrs. John Peco, Jim Lemig, and Art Youmann visited Radiation during the week of 4 February 1963. Project progress was reviewed, and a discussion and review of the Test and Evaluation Plan was held. The two engineering Test Models were examined and operationally demonstrated.

The fact that some of the tests in the Test and Evaluation Plan were redundant was discussed, and it was tentatively agreed that it would be desirable to avoid the redundant testing in order to eliminate unnecessary and time-consuming testing, both at Ft. Monmouth and at Radiation.

John Peco and Jim Lemig requested:

(1) Preliminary patching information for the operational modes required by the test and evaluation plan (2) a preliminary parts list (3) the detailed specifications for the keyer transistor (4) an investigation into a protective circuit in the keyer and (5) information on the reliability of the lamp being used as a protective device in the output circuitry. Drawings and/or written information was supplied on Items 1 through 3, and a telecon was held with J. Peco concerning Items 4 and 5. Items 4 and 5 will be further discussed after the two engineering test models have been evaluated.

A second conference was held at Radiation on 7 March 1963. Mr. Ed DeForrest represented USAERDL, and R. Squires and D. Balser represented Radiation. The purpose of the conference was to discuss the mechanical problems of the TH-38 test models, specifically the mechanical resonance. Mr. DeForrest inspected the unit, and also witnessed vibration testing of the unit. He was given photographs of the unit, and returned to USAERDL to prepare an evaluation report of the mechanical problems presented in the unit. His conclusions at Radiation were that the unit did not presently satisfy the vibration specification, and that a mechanical redesign would be desirable if USAERDL project personnel would allow the time.

(2) Several telecons were held between J. Peco of USAERDL and R. Squires and W. Premaza of Radiation. The majority of these conferences

were held in order to discuss problems relative to the mechanical resonance present in the TH-38 Test Models. A later telecon between J. Futerfas and W. Premaza established that Radiation should proceed to insure that the resonance problem be eliminated.

IV FACTUAL DATA

A Checkout of Engineering Test Models

The two engineering test models were checked electrically in the following basic modes required by the specification:

- (1) Polar to Neutral
- (2) Neutral to Polar
- (3) Polar to Polar
- (4) Neutral to Neutral

Data taken during these tests verified that the units were performing within the specifications. Following is a tabulation of the basic mode tests and the distortion encountered in both units.

UNIT #1 EAST CHANNEL MEASUREMENTS

Input	Output	Max. Distortion	Max. % Distortion
P+M 10 ma 1	o N-M 60 ma	Approx. 250 microseconds	1.9%
N +M 20 ma T	o P+M 20 ma	Approx. 300 microseconds	2.3%
P+M 10 ma T	o P-M 25 ma	Approx. 250 microseconds	1.9%
N +M	o N-M	Approx. 300 microseconds	2.3%
20,40,60 ma	20, 40, 60 ma	•	

UNIT #1 WEST CHANNEL MEASUREMENTS

Input	Output	Max. Distortion	Max. % Distortion
P +M 10 ma To	N +M 60 ma	Approx. 110 microseconds	0.83%
N +M 20 ma To	P +M 20 ma	Approx. 250 microseconds	1.9%
P +M 10 ma To	P -M 25 ma	Approx. 250 microseconds	1.9%
N +M To	N -M	Approx. 250 microseconds	1.9%
20,40,60 ma	20,40,60 ma		

UNIT #2 EAST CHANNEL MEASUREMENTS

Input		Output	Max. Distortion	Max. % Distortion
P +M 10 ma	То	N -M 60 ma	Approx. 160 microseconds	1.2%
N +M 20 ma	To	P -M 25 ma	Approx. 80 microseconds	0.6%
P-+M 10 ma	То	P -M 25 ma	Approx. 40 microseconds	0.3%
N +M	То	N -M	Approx. 160 microseconds	1.2%
20,40,60 ma	,	20,40,60 ma	,	

UNIT #2 WEST CHANNEL MEASUREMENTS

Input	Output	Max. Distortion	Max. % Distortion
P +M 10 ma To	N -M 60 ma	Approx. 250 microseconds	1.9%
N -M 20 ma To	P -M 25 ma	Approx. 40 microseconds	0.3%
P+M 10 ma To	P -M 25 ma	Approx. 60 microseconds	0.45%
N +M To	N-M	Approx. 250 microseconds	1.9%
20,40,60 ma	20,40,60 ma		

NOTE: (1) P = Polar, N = Neutral (2) Measurements made at 100 WPM.

The units were then tested in the following operational modes:

- (1) Full Duplex Polar to Polar
- (2) Half Duplex/Full Duplex Neutral to Polar

These tests were performed in the four-wire mode. Two-wire testing was not necessary, since for the purposes of laboratory testing both the four and two-wire hookups are identical electrically.

The outputs of the respective channels were used to drive 100 wpm printers in the above modes, and test messages were recorded.

Unit #1 was then submitted to testing in the above modes at the temperature extremes required. These tests were run at -45°C and +60°C. No difficulties were encountered at the +60°C temperature. At -45°C the DC to DC converter power supply was not starting reliably. Checks showed that insufficient base drive was being applied due to the downward trend of the transistor betas at this temperature. Accordingly, the base circuit sensistors were decreased from 50 ohms to 25 ohms, effectively doubling the current available for the transistor base. All modes of tests were then normal, and the converter started reliably. The unit was then rechecked at +60°C to insure that the increased drive was not detrimental to the circuit at the higher temperatures and correspondingly higher betas. Operation was completely checked and found to be normal. Line voltage variations from 103 VAC to


125 VAC were applied to the unit at both temperature extremes with no effect on the operation. No significant changes in the distortion measurements were noted at either temperature extreme or either line voltage extreme.

Unit #1 was then submitted to vibration testing according to Section 4 of SCL 4067. Resonance was found in the unit at approximately 35 cycles. The resonance was measured with accelerometers placed at strategic points on the chassis. The main chassis was reworked in an effort to eliminate or shift the resonance outside the undesired range. The rework, however, resulted only in a 2 to 3 cycle shift, and did not bring the unit into specification. The testing was then halted since it appeared that further rework of the existing chassis would probably not solve the problem.

B SYSTEM DESIGN

The major portion of this period was devoted to the assembly and testing of the two engineering test models. Due to the failure of the unit to meet the vibration requirements of the specification, however, a large scale mechanical redesign effort was begun. A study was made of the unit resonance problem, and the decision was made to repackage the unit on a more rugged main chassis.

The decision was made to use a cast chassis with strengthening rib



1556-1

Figure I Repeater, Telegraph TH 38 ()/G

sections located at cruc ial points. Also, the heavier components were located strategically on the chassis, so as to take full advantage of the strengthening members. The original shape and dimensions of the unit were retained, but the entire unit will be of heavier structure and more rugged. All design considerations indicate that this chassis will meet the requirements of SCIL 40 67 relative to service conditions.

Work progress ed on the redesign to a point where bids were received for the pattern making and casting of the new chassis. The bids received indicated that the new classis design will afford the Signal Corps a more economical unit in the event that a number of follow-on units are constructed. The cost per unit of the initial units will be slightly higher, however, since the casting approachmentails making new drawings and the fabrication of a casting pattern, both of which are fairly costly items. However, the long range benefits of this approach as far as follow-on work is concerned, should be obvious.

V CONCLUSIONS

The electrical testing of the units, using the Test and Evaluation

Plan as a guide, indicated that the units will satisfy the electrical operating

requirements of SCL-4067. The redesign of the main chassis and the re
packaging of the unit should insure that the unit will meet the mechanical

design specifications.

VI PROGRAM FOR NEXT INTERVAL

The new chassis will be procured and two new engineering test models will be assembled and tested. These units will be submitted to USAERDL for testing to the Test and Evaluation Plan, and for environmental testing.

VII KEY PERSONNEL

Following is a list of key personnel and the hours expended during the report period.

K.	D.	Squires	179
R.	D.	Squires	179
R.	Α.	Cauble	20

DISTRIBUTION LIST

CONTRACT SC-87254

FOURTH QUARTERLY REPORT

OASD (R&E), Rm 3E1065		Commanding Officer	
ATTN: Technical Library		U.S. Army Electronics Material Support	Agency
The Pentagon		ATTN: SELM6-ADJ	- ,
Washington 25, D. C.	1	Fort Monmouth, New Jersey	1
Chief of Research and Developme	nt	Director, Fort Monmouth Office	
OCS, Dept. of the Army		USA Communication & Electronics	
Washington 25, D. C.	1	Combat Development Agency	
		Fort Monmouth, New Jersey	1
Commanding General		Corps of Engineers Liaison Office	
U.S. Army Materiel Command		U. S. Army Electronics R&D Laboratory	•
ATTN: R&D Directorate		Fort Monmouth, New Jersey	1.
Washington 25, D. C.	1		
Commanding General		AFSC Scientific/Technical Liaison Office	е
U.S. Army Electronics Command	l	U.S. Army Electronics R&D Laboratory	
ATTN: AMSEL-AD		Fort Monmouth, New Jersey	1
Fort Monmouth, N. J.	2		
Director, U.S. Naval Research		AFSC Scientific/Technical Liaison Office	е
Laboratory		U.S. Naval Air Development Center	
ATTN: Code 2027		Johnsville, Pennsylvania	1
Washington 25, D. C.	1		
Commanding Officer and Director		Marine Corps Liaison Office	
U.S. Navy Electronics Laboratory	у	U.S. Army Electronics R&D Laboratory	
San Diego 52, California	1	Fort Monmouth, New Jersey	1
Aeronautical Systems Division		Commanding Officer	
ATTN: ASAPRL	1	U.S. Army Electronics R&D Laboratory	
Wright-Patterson Air Force Base	, Ohio	ATTN: Logistics Division(SELRA/NDD) Fort Monmouth, New Jersey	2

DISTRIBUTION LIST (Continued)

Air Force Cambridge Research	Rome Air Development Center
Laboratories	ATTN: RAALD
ATTN: CRZC	Griffiss Air Force Base
L.G. Hanscom Field	New York 1
Bedford, Massachusetts	
Air Force Cambridge Research	Commanding Officer
Laboratories	USA Communication & Electronics Combat
ATTN: CRXL-R	Development Agency
L. G. Hanscom Field	Fort Huachuca
Bedford, Massachusetts 1	Arizona 1
Hq., Electronic Systems Division	Commanding General
ATTN: ESAT, L.G. Hanscom Field	U. S. Army Electronics R&D Activity
Bedford, Massachusetts 1	ATTN: Technical Library
	Fort Huachuca, Arizona 1
Commander	
Armed Services Technical	Commanding Officer
Information Agency	U.S. Army Electronics R&D Laboratory
ATTN: TISIA	ATTN: Director of Research/Engineering
Arlington Hall Station	Fort Monmouth, N. J. 1
Arlington 12, Virginia 1	fort Momitoutil, 14. 0.
Armgton 12, Virginia	
Commanding Officer	Commanding Officer
U. S Army Electronics R&D	U.S. Army Electronics Research &
Laboratory	Development Laboratory
ATTN: Technical Documents Center	ATTN: SELRA/ADJ
Fort Monmouth, N. J.	Fort Monmouth, N. J.
Commanding Officer	Commanding General
U.S. Army Electronics Research	U.S.A. Combat Developments Command
and Development Laboratory	ATTN: CDCMR-E
ATTN: Technical Information Division	Fort Belvoir, Virginia 1
Fort Monmouth, New Jersey 1	· •
Chief, U.S. Army Security Agency	Deputy President
Arlington Hall Station	U.S. Army Security Agency Board
Arlington 12, Virginia 1	Arlington Hall Station
	Arlington 12, Virginia 1
	_

UNCLASSFED 1. Teletype Commerciation Equipment 1. Title: Repeate, Telegraph 11. E. Sudan 11. U. S. Anger 12. UNCLASSFED	UNCLASSIFED 1. Teletype Communications Equipment 1. Title: Repeater, Telegraph 11. E. Souler 11. E. Souler 11. E. Souler 12. Amy Signal Reservices 13. Our Signal Reservices 14. Communication and Mammanian Leadoursery, For Mammanian Leadoursery, For Mammanian Leadoursery, For Communication Leadoursery,
Registrion homogeneousled, Multicorens, Florida. Registria, TELEGOLAMY HIV-38 (1/50 pt. Squires. Charmerly Report No. 4, Registria, TELEGOLAMY HIV-38 (1/50 pt. Squires. Charmerly Report No. 4, Desamble 1982 frough! Entropy 1983 on falsagenia Registria. Signal Entropy 1983 on falsagenia Registria. Signal Corps Communt Del-20875, SCEEZS (Inclandificial registrial. The suppose of Chris project is to design, develop and fubricose 20 falsagenia TH-38 (1/50. The reposed will generals in the models full dustriase and half designed chall designed in the models full dustrians and half designed in the full designed charmers in the models full dustrians and half designed in the full designed in the charmers are not secured to the full designed in the full designed and broadcast of the full designed and design was began in order to insure compliance with the me charifical employer.	Engineerin Incorporated, Malthorms, Florida Engineerin Incorporated, Malthorms, Florida December 1962 (Ford) Edward (N. V. C. Spaines. Countedly Report No. 4, EEFEARE, TELECLAM TH-28 (N. V. C. M. Spaines. Countedly Reports Floridaes Including Illustration. Signel Corps Contract DA-3M079, SCB7254 Uncleasified report. The purpose of this protect is to delayed, develope and telectrics of Isla- graph Reports 14-38 (N. V. The reporter will operate in two modes full de- place and hold telegrae-1-NI delayed. Using the converter, circuit of differing characteristics may be interconnected and normal traffic aetablished. A prima requisite is no achieve MEAN -TIME - RETWEEN -FAILURE of 57,000 hours. During this phase, the first two engineering test models were assembled and tomach, and unit resonances of approximately 35 cycles was desected. A mechanical nedesign was bagan in order to insure compliance with the mechani- cal requirements of SCL-4667.
UNCLASSIFED 1. Telesype Communication Equipment 2. Title: Equator: Telegraph 11. E. Santa (MG 11. E. Sa	UNCLASSIFIED 1. Teletype Communications Equipment 1. Title: Repeater, Telegraph 11. E. Septem 11. E. Septem 11. U. S. Amy Signet Research and 12. Many Signet Research and 13. Manuality, New Jerry, Fort Newmorth, New Jerry, Fort New Services Technical Information Agency UNCLASSIFIED
hadrien kompenend, Malkamm, Florida Bedinian kompenend, Malkamm, Florida BEFATE, TELEGRANI 11-38 (VG by E. Series. Country) Report No. 4, BEFATE, TELEGRANI 11-38 (VG by E. Series. Country) Report No. 4, BEFATE, TELEGRANI 11-38 (VG by E. Series. Country) Report No. 4, BEFATE, THE property No. 4 of Telegraph Reports Price of the Series Best No. 4 of Telegraph Report I is a forting, decorate and festivated for graph Reports of this property will appear in two modes full de- ports Reports of this property of the Series Reports of the Series Best Reports of the Series Series Series Reports of Telegraph Reports of the Series Reports of the Series of the Series Series Series Series Series Best Reports of the Series of Series Reports of the Series of Series Series Series Series Best Reports of the Series of Series Best Reports of the Series of Series Best Reports of the Series of Series Series Best Reports of the Series of Series Best Reports of the Series of Series Series Series Series Best Reports of the Series of Series Best Reports of the Series of Series Best Reports of the Series of Series of Series Best Reports of the Series of Series Series Best Reports of Series Series of Series Best Reports of	Indicates beampounds, Multimores, Florida. INTERCATE, TELEGOLANI 111-38 (VG PR. Septem. Countrally Report No. 4, INTERCATES, TELEGOLANI 111-38 (VG PR. Septem. Countrally Report No. 4, Countrall

-